




Dew point set FA 410

Ready for upgrading with data logger, ethernet interface and 2nd sensor input


Dew point set FA 410

consisting of:



Special features

- System ready for plug-in: everything completely wired
- No time-consuming studying of the instruction manual
- 2 alarm contacts (230 VAC, 3 A) pre- and main-alarm freely adjustable
- 4...20 mA analogue output
- Optical alarm: Red flashing
- Parallel indication % RH, °C, °C_{td}



Technical data DS 300

Dimensions:	118 x 115 x 93 mm, IP 65 (wall housing) 92 x 92 x 70 mm, IP 65 (panel mounting)
Inputs:	2 digital inputs for FA 410 resp. VA 400
Interface:	USB
Keypad:	4 keys
Power supply:	100...240 VAC, 50-60 Hz
Accuracy:	see FA 410 page 6
Alarm outputs:	2 relays, 230 VAC, 3 A
Operating temp.:	0...50 °C
Transport temperature:	-20...70 °C
OPTIONS	
Data logger:	1 million meas. values start/stop time, meas. rate freely adjustable

Description	Order no.
Dew point set FA 410 for adsorption dryers (-80...20 °Ctd)	0600 0410
Dew point set FA 410 for refrigeration dryers (-20...50 °Ctd)	0600 0412
Option:	
Integrated data logger for 1 million measured values	Z500 3001
Ethernet interface	Z500 3005
Alarm unit mounted at wall housing	Z500 0003
Alarm unit for external mounting with 5 m cable	Z500 0004
Additional accessories:	
CS Soft Professional software for data evaluation in graphic and table form including USB interface	0554 7010
Precision calibration at -40 °Ctd including ISO certificate	0699 3396
Precision calibration at 0 °C and 10 °Ctd including ISO certificate	3200 0003
Control and calibration set 11.3 % RH	0554 0002
Control and calibration set 33 % RH	0554 0004
Control and calibration set 75.3 % RH	0554 0005